



miamidade.gov

November 14, 2013

### RESPONSE LETTER NO. 1 TO REQUEST FOR INFORMATION

Project Title: Drainage Improvement for SW 157<sup>th</sup> Avenue Canal Interconnect

Project No.: 20130213

Fax from Mr. Rick Rodriguez, RJR Construction, Inc.; dated November 13, 2013 (attached)

RESPONSE: 1)

The canal will not be wider than 3 feet. Based on the soil testing and the existence of a slab covered canal in site, which we are connecting to, the current detail is sufficient. However, if some unforeseen condition requires a different shape canal, a proper detail will be provided.

The concrete slab will be 9-inches thick. The main bars will be #6 @ 6-inches 2) (main) and the distributive bars will be #4 @ 11-inches (dist).

### **END OF REQUEST FOR INFORMATION**

Sincerely,

Frank Aira, P.E., CFM Division Manager, PWWM

FA:lc

Luis O. Perez, P.E., PWWM C: Alfredo E. Munoz, P.E., PWWM James P. Ferreira, P.E., PWWM Daryl Hildoer, P.E., PWWM Tony Moreno, PWWM Jose Gutierrez, PWWM Ultimo de Oliveira, ISD Clerk of the Board Project File

PAGE 01

3052671899

7025 SW 19th Terrace Miami FI 33155 Info@rirconstruction.com 305 244 1837 305 267 1899 fax

## **RJR Construction Inc.**

# Fax RFI

To:	MD Public Works and Waste Management	From:	Rick Rodriguez
Att:	James P Ferreira	Date:	11/13/13
Fax	305 375 2931	Pages:	1
Re:	Drainage Improvements to SW 157 <sup>th</sup> Ave, Canal RPQ No. 20130213	CC:	Valveo2@miamidade.go
Please address the following concerns:  Question 1: page 50; 3- Engineering Evaluation and Recommendations  3.1 Description of soil conditions - in second paragraph reads " The limestone stratum began from a few inches to 8 ft below ground"  3.3 Recommendations - The depth of 10-ft makes the excavation deep and side supports may be necessary			

#### Question 2:

Sheet 2 of the plans SLAB COVER CANAL DETAIL the numbers are not very legible on plans. Please confirm that the slab is 8" thick; the longitudinal bars are # 6 at 8" and the bars perpendicular to the trench are #4 at 11". Please note that if this is so there is less reinforcing being provided in the direction of highest bending moment.

RECEIVED

NOV 13 2013

PWD/Contracts and Specifications Initials: